DOC. NO. 535
TOTAL PAGES 5
COPY 5 of 9

P+E
OTTEN

OSA -2975-64

16 June 1964

TO: ▮▮▮▮▮▮▮▮▮

FROM: ▮▮▮▮▮▮▮▮▮▮▮▮▮▮▮

REF: Area 6217 (10 Jun 64) Para. 7. Task 2030

Attachments #1 (one sheet), #2 (two sheets) and #3 (one sheet) contain our available file background on the Vac-Ion pump power being fed through Plug Q5.

The 13 Sep 63 phonecon (Att. 1) led to ▮▮▮▮▮▮▮ 18 Sep 63 **STATINTL** letter to me (Att. 2-A and 2-B). Since we have received no amendment to Don's letter, all our systems are wired to accomodate the schematic (Att. 2-B). Per my notes of 7 Oct 63 meeting with Don (Att. 3), only the fuse shown in the schematic was eliminated.

Since frame rewiring is time consuming and expensive, we propose **STATINTL** to (1) leave our system as it is now and (2) have ▮▮▮▮▮▮▮ wire plug **STATINTL** Q5 in accordance with the agreement. If this proposed course is impossible, we will investigate alternative courses, but any alternative will have to be new scope contractually.

STATINTL

mb STATINTL

cc: ▮▮▮▮▮▮▮